
CAPE COD PERFECTION SUMMARY INSTALLATION GUIDE


6




CAUTION: ALWAYS INSTALL PRODUCT FROM LEFT TO RIGHT AND REMEMBER THAT POLYMER UNDERGOES EXPANSION/CONTRACTION DUE TO TEMPERATURE VARIATIONS. FOR A BETTER LOOK WE RECOMMAND TO INSTALL PRODUCT ON FLAT SURFACES (EX: PLYWOOD PANELS OR OSB PANELS). IF SECTIONS ARE INSTALLED ON A WALL WITH FURRINGS, FURRING STRIPS MUST BE INSTALLED **OBLIQUELY AND SPACED BY 8"(20,32CM).**




Install sections and space equally. Refer to temperature marks that show the outside temperature the 5 closest to that during installation.






Alternate the joints between rows. For a nicer look, we suggest alternating the cutting distance of the first section of every row from 0"(0cm) - 15"(38,1cm) - 30"(76,2cm) - 28"(71,1cm).



If you need to attach the section in an area other than the installation hole, create a 1"(2,54 cm) long slot to allow nailling. Always nail in the middle of the slot.



See QCshake.com for the complete installation guide.